

Ass izspaušanas saraksts

Nr.p.k.	Pk	Koordinātes, LKS-92 TM		Piezīmes
		x	y	
1	0+00,000	258390,638	469293,907	Trases sākums
2	0+20,000	258409,785	469299,686	Trases Pk 0+20
3	0+40,000	258428,931	469305,465	Trases Pk 0+40
4	0+49,732	258438,248	469308,277	Lūzuma punkts
5	0+60,000	258448,104	469311,157	Trases Pk 0+60
6	0+80,000	258467,302	469316,765	Trases Pk 0+80
7	1+00,000	258486,499	469322,374	Trases Pk 1+00
8	1+20,000	258505,697	469327,982	Trases Pk 1+20
9	1+40,000	258524,894	469333,590	Trases Pk 1+40
10	1+60,000	258544,092	469339,199	Trases Pk 1+60
11	1+80,000	258563,290	469344,807	Trases Pk 1+80
12	1+98,910	258581,441	469350,110	Pārejas līknes sākums
13	2+00,000	258582,487	469350,416	Trases Pk 2+00
14	2+20,000	258601,600	469356,301	Trases Pk 2+20
15	2+28,910	258609,984	469359,316	Pārejas līknes beigas/ Līknes sākums R=180
16	2+40,000	258620,204	469363,618	Trases Pk 2+00
17	2+60,000	258637,890	469372,932	Trases Pk 2+00
18	2+69,575	258645,967	469378,074	Līknes beigas/ Pārejas līknes sākums
19	2+80,000	258654,456	469384,122	Trases Pk 2+00
20	2+99,575	258669,860	469396,201	Pārejas līknes beigas
21	3+00,000	258670,191	469396,467	Trases Pk 3+00
22	3+20,000	258685,782	469408,993	Trases Pk 3+20
23	3+40,000	258701,373	469421,519	Trases Pk 3+40
24	3+60,000	258716,965	469434,046	Trases Pk 3+60
25	3+80,000	258732,556	469446,572	Trases Pk 3+80
26	4+00,000	258748,148	469459,098	Trases Pk 4+00
27	4+20,000	258763,739	469471,624	Trases Pk 4+20
28	4+40,000	258779,330	469484,151	Trases Pk 4+40
29	4+60,000	258794,922	469496,677	Trases Pk 4+60
30	4+80,000	258810,513	469509,203	Trases Pk 4+80
31	5+00,000	258826,105	469521,730	Trases Pk 5+00
32	5+20,000	258841,696	469534,256	Trases Pk 5+20
33	5+40,000	258857,287	469546,782	Trases Pk 5+40
34	5+46,161	258862,090	469550,641	Lūzuma punkts
35	5+60,000	258873,103	469559,022	Trases Pk 5+60
36	5+80,000	258889,017	469571,135	Trases Pk 5+80
37	6+00,000	258904,932	469583,248	Trases Pk 6+00
38	6+20,000	258920,847	469595,361	Trases Pk 6+20
39	6+40,000	258936,762	469607,474	Trases Pk 6+40
40	6+60,000	258952,676	469619,586	Trases Pk 6+60
41	6+80,000	258968,591	469631,699	Trases Pk 6+80
42	7+00,000	258984,506	469643,812	Trases Pk 7+00
43	7+20,000	259000,421	469655,925	Trases Pk 7+20
44	7+40,000	259016,336	469668,038	Trases Pk 7+40
45	7+60,000	259032,250	469680,150	Trases Pk 7+60
46	7+61,735	259033,631	469681,201	Lūzuma punkts
47	7+80,000	259048,160	469692,270	Trases Pk 7+80

Nr.p.k.	Pk	Koordinātes, LKS-92 TM		Piezīmes
		x	y	
48	8+00,000	259064,070	469704,389	Trases Pk 8+00
49	8+20,000	259079,979	469716,509	Trases Pk 8+20
50	8+40,000	259095,889	469728,629	Trases Pk 8+40
51	8+60,000	259111,798	469740,748	Trases Pk 8+60
52	8+80,000	259127,708	469752,868	Trases Pk 8+80
53	9+00,000	259143,617	469764,988	Trases Pk 9+00
54	9+20,000	259159,527	469777,107	Trases Pk 9+20
55	9+30,748	259168,077	469783,621	Pārejas līknes sākums
56	9+40,000	259175,446	469789,214	Trases Pk 9+40
57	9+60,000	259191,644	469800,943	Trases Pk 9+60
58	9+62,748	259193,920	469802,483	Pārejas līknes beigas/ Līknes sākums R=260
59	9+80,000	259208,568	469811,591	Trases Pk 9+80
60	10+00,000	259226,260	469820,906	Trases Pk 10+00
61	10+18,864	259243,558	469828,423	Līknes beigas R=260/ Pārejas līknes sākums
62	10+20,000	259244,616	469828,835	Trases Pk 10+20
63	10+40,000	259263,468	469835,509	Trases Pk 10+40
64	10+50,864	259273,799	469838,869	Pārejas līknes beigas
65	10+60,000	259282,494	469841,675	Trases Pk 10+60
66	10+80,000	259301,527	469847,816	Trases Pk 10+80
67	11+00,000	259320,561	469853,957	Trases Pk 11+00
68	11+20,000	259339,595	469860,098	Trases Pk 11+20
69	11+40,000	259358,629	469866,239	Trases Pk 11+40
70	11+60,000	259377,663	469872,380	Trases Pk 11+60
71	11+80,000	259396,697	469878,521	Trases Pk 11+80
72	12+00,000	259415,730	469884,662	Trases Pk 12+00
73	12+06,877	259422,275	469886,774	Līknes sākums R=80
74	12+20,000	259434,379	469891,808	Trases Pk 12+20
75	12+40,000	259450,829	469903,090	Trases Pk 12+40
76	12+48,966	259457,186	469909,406	Līknes beigas R=80
77	12+49,012	259457,217	469909,440	Līknes sākums R=80
78	12+60,000	259465,103	469917,080	Trases Pk 12+60
79	12+80,000	259481,834	469927,943	Trases Pk 12+80
80	12+96,421	259497,242	469933,536	Līknes beigas R=80
81	13+00,000	259500,714	469934,406	Trases Pk 13+00
82	13+20,000	259520,113	469939,269	Trases Pk 13+20
83	13+40,000	259539,513	469944,132	Trases Pk 13+40
84	13+42,059	259541,510	469944,633	Pārejas līknes sākums
85	13+60,000	259558,893	469949,073	Trases Pk 13+60
86	13+72,059	259570,515	469952,290	Pārejas līknes beigas/ Līknes sākums R=400
87	13+80,000	259578,117	469954,584	Trases Pk 13+80
88	13+94,130	259591,526	469959,036	Līknes beigas R=400/ Pārejas līknes sākums
89	14+00,000	259597,051	469961,021	Trases Pk 14+00
90	14+15,130	259611,211	469966,351	Pārejas līknes beigas
91	14+18,763	259614,605	469967,646	Pārejas līknes sākums
92	14+20,000	259615,761	469968,087	Trases Pk 14+20
93	14+39,763	259634,290	469974,961	Pārejas līknes beigas / Līknes sākums R=400
94	14+40,000	259634,513	469975,040	Trases Pk 14+40
95	14+60,000	259653,541	469981,191	Trases Pk 14+60
96	14+80,000	259672,853	469986,384	Trases Pk 14+80

Nr.p.k.	Pk	Koordinātes, LKS-92 TM		Piezīmes
		x	y	
97	15+00,000	259692,400	469990,606	Trases Pk 15+00
98	15+20,000	259712,134	469993,845	Trases Pk 15+20
99	15+35,999	259728,021	469995,723	Līknes beigas R=400 / Pārejas līknes sākums
100	15+40,000	259732,005	469996,095	Trases Pk 15+40
101	15+60,000	259751,955	469997,491	Trases Pk 15+60
102	15+75,999	259767,934	469998,296	Pārejas līknes beigas
103	15+80,000	259771,930	469998,487	Trases Pk 15+80
104	16+00,000	259791,908	469999,440	Trases Pk 16+00
105	16+20,000	259811,885	470000,394	Trases Pk 16+20
106	16+40,000	259831,862	470001,347	Trases Pk 16+40
107	16+60,000	259851,839	470002,301	Trases Pk 16+60
108	16+72,665	259864,490	470002,905	Pārejas līknes sākums
109	16+80,000	259871,817	470003,258	Trases Pk 16+80
110	17+00,000	259891,784	470004,397	Trases Pk 17+00
111	17+02,665	259894,442	470004,585	Pārejas līknes beigas / Līknes sākums R=600
112	17+20,000	259911,711	470006,093	Trases Pk 17+20
113	17+40,000	259931,570	470008,453	Trases Pk 17+40
114	17+60,000	259951,340	470011,473	Trases Pk 17+60
115	17+80,000	259970,998	470015,150	Trases Pk 17+80
116	18+00,000	259990,523	470019,480	Trases Pk 18+00
117	18+14,657	260004,734	470023,066	Līknes beigas / Pārejas līknes sākums
118	18+20,000	260009,892	470024,458	Trases Pk 18+20
119	18+40,000	260029,127	470029,936	Trases Pk 18+40
120	18+44,657	260033,597	470031,241	Pārejas līknes beigas
121	18+60,000	260048,325	470035,545	Trases Pk 18+60
122	18+66,977	260055,022	470037,503	Pārejas līknes sākums
123	18+80,000	260067,524	470041,148	Trases Pk 18+80
124	18+96,977	260083,845	470045,823	Pārejas līknes beigas / Līknes sākums R=1500
125	19+00,000	260086,755	470046,639	Trases Pk 19+00
126	19+20,000	260106,053	470051,890	Trases Pk 19+20
127	19+40,000	260125,420	470056,883	Trases Pk 19+40
128	19+60,000	260144,851	470061,618	Trases Pk 19+60
129	19+80,000	260164,344	470066,093	Trases Pk 19+80
130	19+87,634	260171,800	470067,732	Līknes R=1500 beigas / Pārejas līknes sākums
131	19+97,634	260181,577	470069,833	Pārejas līknes beigas
132	19+97,640	260181,583	470069,835	Pārejas līknes sākums
133	20+00,000	260183,890	470070,328	Trases Pk 20+00
134	20+20,000	260203,422	470074,632	Trases Pk 20+20
135	20+39,640	260222,465	470079,432	Pārejas līknes beigas / Līknes sākums R=350
136	20+40,000	260222,811	470079,528	Trases Pk 20+40
137	20+46,548	260229,103	470081,344	Līknes beigas R=350
138	20+60,000	260241,923	470085,415	Trases Pk 20+60
139	20+80,000	260260,794	470092,037	Trases Pk 20+80
140	20+88,548	260268,826	470094,964	Pārejas līknes beigas
141	21+00,000	260279,582	470098,894	Trases Pk 21+00
142	21+20,000	260298,367	470105,758	Trases Pk 21+20
143	21+40,000	260317,153	470112,622	Trases Pk 21+40
144	21+60,000	260335,938	470119,485	Trases Pk 21+60
145	21+80,000	260354,723	470126,349	Trases Pk 21+80

Nr.p.k.	Pk	Koordinātes, LKS-92 TM		Piezīmes
		x	y	
146	22+00,000	260373,509	470133,213	Trases Pk 22+00
147	22+20,000	260392,294	470140,077	Trases Pk 22+20
148	22+40,000	260411,079	470146,941	Trases Pk 22+40
149	22+40,589	260411,632	470147,143	Lūzuma punkts
150	22+60,000	260429,644	470154,380	Trases Pk 22+60
151	22+80,000	260448,202	470161,836	Trases Pk 22+80
152	23+00,000	260466,760	470169,293	Trases Pk 23+00
153	23+07,836	260474,031	470172,215	Pārejas līknes sākums
154	23+20,000	260485,321	470176,743	Trases Pk 23+20
155	23+40,000	260503,927	470184,077	Trases Pk 23+40
156	23+47,836	260511,245	470186,880	Pārejas līknes beigas / Līknes sākums R=1000
157	23+60,000	260522,646	470191,119	Trases Pk 23+60
158	23+80,000	260541,502	470197,786	Trases Pk 23+80
159	24+00,000	260560,487	470204,075	Trases Pk 24+00
160	24+20,000	260579,594	470209,984	Trases Pk 24+20
161	24+40,000	260598,815	470215,509	Trases Pk 24+40
162	24+60,000	260618,143	470220,648	Trases Pk 24+60
163	24+80,000	260637,570	470225,400	Trases Pk 24+80
164	25+00,000	260657,088	470229,762	Trases Pk 25+00
165	25+05,794	260662,759	470230,953	Līknes beigas R=1000 / Pārejas līknes sākums
166	25+20,000	260676,688	470233,745	Trases Pk 25+20
167	25+40,000	260696,337	470237,476	Trases Pk 25+40
168	25+45,794	260702,033	470238,537	Pārejas līknes beigas
169	25+60,000	260715,998	470241,138	Trases Pk 25+60
170	25+80,000	260735,660	470244,799	Trases Pk 25+80
171	26+00,000	260755,323	470248,460	Trases Pk 26+00
172	26+20,000	260774,985	470252,121	Trases Pk 26+20
173	26+35,611	260790,331	470254,979	Līknes sākums R=3000
174	26+40,000	260794,646	470255,785	Trases Pk 26+40
175	26+60,000	260814,290	470259,541	Trases Pk 26+60
176	26+80,000	260833,909	470263,427	Trases Pk 26+80
177	27+00,000	260853,501	470267,444	Trases Pk 27+00
178	27+12,720	260865,949	470270,067	Līknes beigas R=3000
179	27+20,000	260873,068	470271,583	Trases Pk 27+20
180	27+40,000	260892,630	470275,748	Trases Pk 27+40
181	27+60,000	260912,191	470279,913	Trases Pk 27+60
182	27+80,000	260931,753	470284,079	Trases Pk 27+80
183	28+00,000	260951,314	470288,244	Trases Pk 28+00
185	28+20,000	260970,876	470292,409	Trases Pk 28+20
186	28+40,000	260990,437	470296,575	Trases Pk 28+40
187	28+60,000	261009,999	470300,740	Trases Pk 28+60
188	28+80,000	261029,560	470304,905	Trases Pk 28+80
189	28+83,917	261033,391	470305,721	Līknes sākums R=7500
190	29+00,000	261049,125	470309,053	Trases Pk 29+00
191	29+20,000	261068,701	470313,151	Trases Pk 29+20
192	29+40,000	261088,288	470317,196	Trases Pk 29+40
193	29+60,000	261107,885	470321,188	Trases Pk 29+60
194	29+80,000	261127,493	470325,129	Trases Pk 29+80
195	30+00,000	261147,111	470329,017	Trases Pk 30+00

Nr.p.k.	Pk	Koordinātes, LKS-92 TM		Piezīmes
		x	y	
197	30+20,000	261166,740	470332,853	Trases Pk 30+20
198	30+40,000	261186,379	470336,636	Trases Pk 30+40
199	30+60,000	261206,028	470340,368	Trases Pk 30+60
200	30+80,000	261225,687	470344,046	Trases Pk 30+80
201	30+92,436	261237,916	470346,307	Līknes beigas R=7500
202	31+00,000	261245,354	470347,676	Trases Pk 31+00
203	31+20,000	261265,024	470351,296	Trases Pk 31+20
204	31+40,000	261284,694	470354,916	Trases Pk 31+40
205	31+60,000	261304,363	470358,536	Trases Pk 31+60
207	31+80,000	261324,033	470362,156	Trases Pk 31+80
208	32+00,000	261343,703	470365,776	Trases Pk 32+00
209	32+20,000	261363,373	470369,395	Trases Pk 32+20
210	32+40,000	261383,042	470373,015	Trases Pk 32+40
211	32+60,000	261402,712	470376,635	Trases Pk 32+60
212	32+80,000	261422,382	470380,255	Trases Pk 32+80
213	33+00,000	261442,051	470383,875	Trases Pk 33+00
214	33+20,000	261461,721	470387,495	Trases Pk 33+20
215	33+40,000	261481,391	470391,115	Trases Pk 33+40
216	33+60,000	261501,060	470394,735	Trases Pk 33+60
217	33+80,000	261520,730	470398,354	Trases Pk 33+80
218	34+00,000	261540,400	470401,974	Trases Pk 34+00
219	34+20,000	261560,069	470405,594	Trases Pk 34+20
221	34+33,889	261573,729	470408,108	Pārejas līknes sākums
222	34+40,000	261579,739	470409,216	Trases Pk 34+40
223	34+57	261596,6401	470412,4517	Trases beigas

Sastādīja:

Gaidis Beitiņš

Pārbaudīja:

Aigars Buķevics