

## Ielas izbūves risinājumu izspaušanas saraksts

Nr.p.k.	Pk	Koordinātes, LKS-92 TM		Piezīmes
		x	y	
1	0+00,000	262199,255	496715,466	Trases sākums
2	0+02,348	262201,203	496714,154	Līknes sākums R=20
3	0+09,310	262207,532	496711,338	Līknes beigas R=20
4	0+20,000	262217,903	496708,748	Trases Pk 0+20
5	0+40,000	262237,307	496703,903	Trases Pk 0+40
6	0+60,000	262256,711	496699,058	Trases Pk 0+60
7	0+69,544	262265,971	496696,746	Lūzuma punkts
8	0+80,000	262276,158	496694,389	Trases Pk 0+80
9	1+00,000	262295,643	496689,881	Trases Pk 1+00
10	1+20,000	262315,128	496685,372	Trases Pk 1+20
11	1+40,000	262334,614	496680,864	Trases Pk 1+40
12	1+58,674	262352,807	496676,655	Līknes sākums R=200
13	1+60,000	262354,098	496676,351	Trases Pk 1+60
14	1+66,401	262360,299	496674,768	Līknes beigas R=200
15	1+80,000	262373,420	496671,193	Trases Pk 1+80
16	1+89,343	262382,435	496668,737	Līknes sākums R=300
17	2+00,000	262392,765	496666,119	Trases Pk 2+00
18	2+20,000	262412,374	496662,202	Trases Pk 2+20
19	2+40,000	262432,200	496659,600	Trases Pk 2+40
20	2+57,520	262449,677	496658,411	Līknes beigas R=300
21	2+60,000	262452,155	496658,315	Trases Pk 2+60
22	2+80,000	262472,140	496657,540	Trases Pk 2+80
23	3+00,000	262492,125	496656,765	Trases Pk 3+00
24	3+20,000	262512,110	496655,990	Trases Pk 3+20
25	3+33,901	262526,000	496655,452	Līknes sākums R=60
26	3+40,000	262532,072	496654,906	Trases Pk 3+40
27	3+60,000	262551,049	496648,889	Trases Pk 3+60
28	3+71,053	262560,366	496642,971	Līknes beigas R=60
29	3+80,000	262567,445	496637,500	Trases Pk 3+80
30	4+00,000	262583,270	496625,270	Trases Pk 4+00
31	4+20,000	262599,095	496613,040	Trases Pk 4+20
32	4+40,000	262614,920	496600,810	Trases Pk 4+40
33	4+60,000	262630,745	496588,580	Trases Pk 4+60
34	4+80,000	262646,570	496576,351	Trases Pk 4+80
35	5+00,000	262662,395	496564,121	Trases Pk 5+00
36	5+20,000	262678,220	496551,891	Trases Pk 5+20
37	5+25,639	262682,681	496548,443	Lūzuma punkts
38	5+40,000	262694,131	496539,773	Trases Pk 5+40
39	5+60,000	262710,076	496527,700	Trases Pk 5+60
40	5+80,000	262726,020	496515,627	Trases Pk 5+80
41	6+00,000	262741,965	496503,554	Trases Pk 6+00
42	6+20,000	262757,910	496491,480	Trases Pk 6+20
43	6+40,000	262773,855	496479,407	Trases Pk 6+40
44	6+60,000	262789,800	496467,334	Trases Pk 6+60
45	6+80,000	262805,744	496455,261	Trases Pk 6+80
46	7+00,000	262821,689	496443,187	Trases Pk 7+00
47	7+02,637	262823,792	496441,596	Lūzuma punkts

Nr.p.k.	Pk	Koordinātes, LKS-92 TM		Piezīmes
		x	y	
48	7+20,000	262837,990	496431,601	Trases Pk 7+20
49	7+40,000	262854,344	496420,089	Trases Pk 7+40
50	7+60,000	262870,699	496408,577	Trases Pk 7+60
51	7+80,000	262887,053	496397,065	Trases Pk 7+80
52	8+00,000	262903,408	496385,553	Trases Pk 8+00
53	8+20,000	262919,762	496374,040	Trases Pk 8+20
54	8+23,136	262922,326	496372,236	Lūzuma punkts
55	8+40,000	262935,973	496362,327	Trases Pk 8+40
56	8+60,000	262952,156	496350,575	Trases Pk 8+60
57	8+80,000	262968,339	496338,824	Trases Pk 8+80
58	9+00,000	262984,523	496327,072	Trases Pk 9+00
59	9+20,000	263000,706	496315,321	Trases Pk 9+20
60	9+40,000	263016,728	496303,687	Trases beigas

Sastādīja:

Gaidis Beitiņš

Pārbaudīja:

Aigars Buķevics