

Ass izspraušanas saraksts

Nr.p.k.	Pk	Koordinātes, LKS-92 TM		Piezīmes
		x	y	
1	16+50,000	259333,465	482876,634	Trases sākums
2	16+94,671	259312,072	482915,849	Ass lūzuma punkts
3	17+47,907	259285,794	482962,148	Ass lūzuma punkts
4	19+10,372	259207,016	483104,235	Ass lūzuma punkts
5	20+27,661	259149,718	483206,576	Līknes sākums R=19
6	20+58,768	259158,135	483233,016	Līknes beigas R=19
7	20+79,866	259177,188	483242,079	Līknes sākums R=300
8	20+94,978	259190,992	483248,224	Līknes beigas R=300
9	21+11,997	259206,710	483254,752	Līknes sākums R=2000
10	22+81,478	259360,288	483326,306	Līknes beigas R=2000
11	27+08,124	259739,041	483522,708	Līknes sākums R=300
12	27+67,313	259793,925	483544,612	Līknes beigas R=300
13	28+10,692	259835,602	483556,645	Līknes sākums R=800
14	29+59,024	259973,494	483610,730	Līknes beigas R=800
15	30+51,598	260056,176	483652,356	Līknes sākums R=450
16	31+57,003	260143,933	483710,315	Līknes beigas R=450
17	32+92,732	260247,681	483797,830	Līknes sākums R=300
18	33+84,935	260326,118	483845,603	Līknes beigas R=300
19	41+80,354	261060,780	484150,501	Līknes sākums R=900
20	43+48,692	261221,372	484200,154	Līknes beigas R=900
21	44+93,807	261363,409	484229,886	Ass lūzuma punkts
22	45+61,630	261430,018	484242,660	Ass lūzuma punkts
23	47+05,881	261571,766	484269,412	Ass lūzuma punkts
24	49+47,424	261808,398	484317,871	Līknes sākums R=400
25	51+23,023	261982,564	484314,823	Līknes beigas R=400
26	52+20,045	262076,873	484292,043	Ass lūzuma punkts
27	55+00,000	262348,237	484223,219	Trases beigas

Sastādīja:

Aigars Buķevics