

## Ass izspaušanas saraksts

| Nr.p.k. | Pk       | Koordinātes, LKS-92 TM |            | Piezīmes            |
|---------|----------|------------------------|------------|---------------------|
|         |          | x                      | y          |                     |
| 1       | 0+00,000 | 288005,957             | 480361,352 | Trases sākums       |
| 2       | 0+05,785 | 288007,596             | 480366,901 | Līknes sākums R=15  |
| 3       | 0+18,399 | 288015,557             | 480376,205 | Līknes beigas R=15  |
| 4       | 0+20,000 | 288017,004             | 480376,89  | Trases Pk 0+20      |
| 5       | 0+40,000 | 288035,077             | 480385,456 | Trases Pk 0+40      |
| 6       | 0+60,000 | 288053,15              | 480394,021 | Trases Pk 0+60      |
| 7       | 0+80,000 | 288071,223             | 480402,586 | Trases Pk 0+80      |
| 8       | 1+00,000 | 288089,296             | 480411,152 | Trases Pk 1+00      |
| 9       | 1+20,000 | 288107,369             | 480419,717 | Trases Pk 1+20      |
| 10      | 1+40,000 | 288125,443             | 480428,282 | Trases Pk 1+40      |
| 11      | 1+60,000 | 288143,516             | 480436,848 | Trases Pk 1+60      |
| 12      | 1+80,000 | 288161,589             | 480445,413 | Trases Pk 1+80      |
| 13      | 2+00,000 | 288179,662             | 480453,978 | Trases Pk 2+00      |
| 14      | 2+20,000 | 288197,735             | 480462,543 | Trases Pk 2+20      |
| 15      | 2+40,000 | 288215,808             | 480471,109 | Trases Pk 2+40      |
| 16      | 2+60,000 | 288233,881             | 480479,674 | Trases Pk 2+60      |
| 17      | 2+80,000 | 288251,954             | 480488,239 | Trases Pk 2+80      |
| 18      | 3+00,000 | 288270,027             | 480496,805 | Trases Pk 3+00      |
| 19      | 3+20,000 | 288288,1               | 480505,37  | Trases Pk 3+20      |
| 20      | 3+38,415 | 288304,741             | 480513,257 | Lūzuma punkts       |
| 21      | 3+40,000 | 288306,176             | 480513,93  | Trases Pk 3+40      |
| 22      | 3+60,000 | 288324,283             | 480522,423 | Trases Pk 3+60      |
| 23      | 3+80,000 | 288342,39              | 480530,917 | Trases Pk 3+80      |
| 24      | 4+00,000 | 288360,497             | 480539,41  | Trases Pk 4+00      |
| 25      | 4+20,000 | 288378,603             | 480547,904 | Trases Pk 4+20      |
| 26      | 4+40,000 | 288396,71              | 480556,397 | Trases Pk 4+40      |
| 27      | 4+60,000 | 288414,817             | 480564,891 | Trases Pk 4+60      |
| 29      | 4+67,507 | 288421,614             | 480568,079 | Lūzuma punkts       |
| 30      | 4+80,000 | 288432,884             | 480573,47  | Trases Pk 4+80      |
| 31      | 5+00,000 | 288450,925             | 480582,101 | Trases Pk 5+00      |
| 32      | 5+20,000 | 288468,967             | 480590,731 | Trases Pk 5+20      |
| 33      | 5+40,000 | 288487,009             | 480599,362 | Trases Pk 5+40      |
| 34      | 5+46,836 | 288493,176             | 480602,312 | Līknes sākums R=690 |
| 35      | 5+60,000 | 288504,996             | 480608,106 | Trases Pk 5+60      |
| 36      | 5+80,000 | 288522,738             | 480617,337 | Trases Pk 5+80      |
| 37      | 6+00,000 | 288540,204             | 480627,078 | Trases Pk 6+00      |
| 38      | 6+20,000 | 288557,381             | 480637,321 | Trases Pk 6+20      |
| 39      | 6+40,000 | 288574,254             | 480648,058 | Trases Pk 6+40      |
| 40      | 6+60,000 | 288590,808             | 480659,28  | Trases Pk 6+60      |
| 41      | 6+80,000 | 288607,031             | 480670,976 | Trases Pk 6+80      |
| 42      | 7+00,000 | 288622,907             | 480683,138 | Trases Pk 7+00      |
| 43      | 7+20,000 | 288638,425             | 480695,755 | Trases Pk 7+20      |
| 44      | 7+40,000 | 288653,57              | 480708,816 | Trases Pk 7+40      |
| 45      | 7+60,000 | 288668,33              | 480722,311 | Trases Pk 7+60      |
| 46      | 7+80,000 | 288682,693             | 480736,227 | Trases Pk 7+80      |
| 47      | 8+00,000 | 288696,647             | 480750,555 | Trases Pk 8+00      |
| 48      | 8+20,000 | 288710,179             | 480765,28  | Trases Pk 8+20      |
| 49      | 8+40,000 | 288723,28              | 480780,392 | Trases Pk 8+40      |
| 50      | 8+50,423 | 288729,932             | 480788,416 | Līknes beigas R=690 |
| 51      | 8+60,000 | 288735,988             | 480795,835 | Trases Pk 8+60      |

| Nr.p.k. | Pk        | Koordinātes, LKS-92 TM |             | Piezīmes            |
|---------|-----------|------------------------|-------------|---------------------|
|         |           | x                      | y           |                     |
| 52      | 8+80,000  | 288748,636             | 480811,328  | Trases Pk 8+80      |
| 53      | 9+00,000  | 288761,283             | 480826,821  | Trases Pk 9+00      |
| 54      | 9+20,000  | 288773,931             | 480842,314  | Trases Pk 9+20      |
| 55      | 9+40,000  | 288786,578             | 480857,807  | Trases Pk 9+40      |
| 56      | 9+60,000  | 288799,226             | 480873,3    | Trases Pk 9+60      |
| 57      | 9+80,000  | 288811,874             | 480888,794  | Trases Pk 9+80      |
| 58      | 10+00,000 | 288824,521             | 480904,287  | Trases Pk 10+00     |
| 59      | 10+00,733 | 288824,985             | 480904,854  | Lūzuma punkts       |
| 60      | 10+20,000 | 288837,25              | 480919,713  | Trases Pk 10+20     |
| 61      | 10+40,000 | 288849,982             | 480935,137  | Trases Pk 10+40     |
| 62      | 10+60,000 | 288862,714             | 480950,561  | Trases Pk 10+60     |
| 63      | 10+80,000 | 288875,445             | 480965,986  | Trases Pk 10+80     |
| 64      | 11+00,000 | 288888,177             | 480981,41   | Trases Pk 11+00     |
| 65      | 11+20,000 | 288900,909             | 480996,834  | Trases Pk 11+20     |
| 66      | 11+24,558 | 288903,81              | 481000,349  | Līknes sākums R=170 |
| 67      | 11+40,000 | 288914,168             | 481011,795  | Trases Pk 11+40     |
| 68      | 11+60,000 | 288929,048             | 481025,141  | Trases Pk 11+60     |
| 69      | 11+80,000 | 288945,393             | 481036,648  | Trases Pk 11+80     |
| 70      | 12+00,000 | 288962,974             | 481046,156  | Trases Pk 12+00     |
| 71      | 12+07,324 | 288969,675             | 481049,112  | Līknes beigas R=170 |
| 72      | 12+12,800 | 288974,732             | 481051,213  | Līknes sākums R=100 |
| 73      | 12+20,000 | 288981,474             | 481053,735  | Trases Pk 12+20     |
| 74      | 12+40,000 | 289000,951             | 481058,129  | Trases Pk 12+40     |
| 75      | 12+53,175 | 289014,096             | 481058,865  | Līknes beigaš R=100 |
| 76      | 12+60,000 | 289020,921             | 481058,798  | Trases Pk 12+60     |
| 77      | 12+80,000 | 289040,92              | 481058,6    | Trases Pk 12+80     |
| 78      | 13+00,000 | 289060,919             | 481058,403  | Trases Pk 13+00     |
| 79      | 13+20,000 | 289080,918             | 481058,205  | Trases Pk 13+20     |
| 80      | 13+40,000 | 289100,917             | 481058,008  | Trases Pk 13+40     |
| 81      | 13+60,000 | 289120,916             | 481057,81   | Trases Pk 13+60     |
| 82      | 13+80,000 | 289140,915             | 481057,613  | Trases Pk 13+80     |
| 83      | 14+00,000 | 289160,914             | 481057,415  | Trases Pk 14+00     |
| 84      | 14+20,000 | 289180,913             | 481057,218  | Trases Pk 14+20     |
| 85      | 14+40,000 | 289200,912             | 481057,02   | Trases Pk 14+40     |
| 86      | 14+60,000 | 289220,911             | 481056,822  | Trases Pk 14+60     |
| 87      | 14+80,000 | 289240,91              | 481056,625  | Trases Pk 14+80     |
| 88      | 15+00,000 | 289260,909             | 481056,427  | Trases Pk 15+00     |
| 89      | 15+20,000 | 289280,908             | 481056,23   | Trases Pk 15+20     |
| 90      | 15+40,000 | 289300,907             | 481056,032  | Trases Pk 15+40     |
| 91      | 15+60,000 | 289320,906             | 481055,835  | Trases Pk 15+60     |
| 92      | 15+80,000 | 289340,905             | 481055,637  | Trases Pk 15+80     |
| 93      | 16+00,000 | 289360,904             | 481055,44   | Trases Pk 16+00     |
| 94      | 16+20,000 | 289380,903             | 481055,242  | Trases Pk 16+00     |
| 95      | 16+40,000 | 289400,902             | 481055,044  | Trases Pk 16+00     |
| 96      | 16+56,200 | 289417.1979            | 481054.8845 | Trases beigas       |

Sastādīja:

Gaidis Beitiņš

Pārbaudīja:

Aigars Buķevics